

SUMMUM 3200 SERIES

formerly EPOXY PLUS Pearl 100 % acrylic Epoxy fortified

zero

VOC

DESCRIPTION

Summum 3200 pearl finish is a Zero VOC 100% acrylic paint fortified with siliconized epoxy, of superior quality for indoor and outdoor use. It is easy to apply, without spattering and dries quickly. **Summum 3200** can be used for commercial, institutionnal and residential projects.

USE						LIMITATIONS			
This paint is applicable on interior and exterior surfaces.						Avoid application in all temperatures under 10°C			
Summ	um 3200 m	ust be	applie	d to	surfaces that have been well				
prepared and properly primed. It is recommended for drywall						Wait 15 days before proceeding with the first cleaning			
wood, cement walls as well as concrete blocks, doors and trims						Do not mix with other paints			
wood (see LIMITATIONS), aluminum, pre-painted steel, galvanized						To prevent warping of vinyl siding, do not use a colour			
steel, and vinyl (see RECOMMENDED PRIMER). Its addition of						darker than the original.			
iliconi	sed epoxy	offers	excep	tiona	al resistance allowing easy	Interior wo	od surfaces or	nly	
cleanin	g in high tra	affic are	eas.						
CHAR		TICS				TECHNIC		IOITAN	N
 Ideal for LEED projects or any other projects requiring Zero VOC paints 						DRYING Reco		at: To touch	
						TIME	3-6 hours		30 minutes
						At 25° Celsius	Relative humi	dity at 50%	6 May differ depending on
Excep	otional levell	ing and	d very	smoo	oth finish.	the colour			
 Offer excellent resistance to cleaning products. Reaches its full cure only 15 days after application. 						SURFACE COVERAGE		42 - 51 m² (450 - 550 ft²)	
						(for 3.78 L)		May vary depending on the surface	
								porosity	
React	ies its full ci	lie only	/ 15 Ua <u>r</u>	ys art	er application.	Recommended film		Wet : 2.9 - 3.6 mils	
Clina	s to well-pre	nared	surface	as wi	thout the need for a primer	thickness		Dry : 1.02 - 1.24 mils	
		•			RECOMMENDED PRIMER).	Cleaning		Lukewarm soapy water	
					,	Resin		100% acrylic epoxy fortified	
• Delay the growth of mould.						Thinner		Water	
						Inflammability		N/A	
Uses	the latest se	lf-cross	s link te	echn	ology	Flash point			
Duarda		alı una la il	1. 			% of solids by weight		49%	
		durapi		праг	ed to conventional paints.	% of solids by volume		35%	
TINTING BASES						VOC (bases 0-3-2)		Zero VOC	
		946 ml	3,78 L	18,9 L	-	VOC (base	s 4-5-6-7)	<100 g/	L
3200-0	White	Х	Х			GLOSS		60 °	20-25%
3200-3	Natural White	х	Х	Х	max. of 3,5 oz of colorant / 3,78 L	Pearl		85 °	40-50%
3200-2	M Base	х	Х		max. of 5 oz of colorant/ 3,78 L			The value is measured based on the	
3200-4	D Base	Х	Х		max. of 8 oz of colorant / 3,78 L	-		white. The value may vary according	
3200-5	A Base	Х	Х		max. of 12 oz of colorant / 3,78 L	STANDARDS			
3200-6	Red Base	Х	Х		max. of 15 oz of colorant / 3,78 L	MPI	Certified cate	egory #15	1
3200-7	Yellow Base	х	Х		max. of 15 oz of colorant / 3,78 L	CFIA	Product app	rouved	

SURFACE PREPARATION	RECOMMENDED PRIMER
The surface must be dry and clean, without dust, oil, grease, rust	Drywall: Use primer; Proline 6070 or Proline Eco 7070.
and soap. On painted surfaces, it is recommended to clean with a	Concrete blocks/rough brick: Apply Proline 6006 block
degreaser (T.S.P.) in order to eliminate any contaminant that may	filler to level the surface or apply Summum 3200 directly.
harm the adhesion or the curing of the product. Thoroughly rinse	New Concrete: Apply Summum 3200 directly onto the
the entire surface. The surfaces must be well sanded and dusted.	surface.
Presence of mould: Clean the affected area with a mixture of 1	New interior wood: Use the Portico 270.
part bleach to 3 parts water. Thoroughly rinse the entire surface.	Pine knots: Seal the pine knots with the Stop Plus 298.
Flaking or peeling paint: Using a scraper, remove the weakened	Red cedar and redwood: Apply one to two coats of Block
and/or loose paint, then sand the edges of the surface to make it	Plus 296 alkyd based.
smooth. A repair compound must be used to fill holes and	Aluminum, galvanized metal, and interior ferrous metal:
uneven surfaces. Sand with a #100 grit sandpaper.	Apply a coat of Adhero Plus 290 or Adhero Hybrid 297.
New drywall: In order to avoid creating an undesirable texture on	Latex paint: No primer is required.
the drywall, the joint compound must not be sanded excessively.	Alkyd paint: Apply an undercoat of Adhero Hybrid 297.
Concrete/Masonry: Wait until the concrete and/or masonry has	Dark colours: Some dark colours may require the
cured at least 30 days before painting it.	application of a dark tinted primer in order to improve
Aluminum, galvanized metal, and interior ferrous metal:	opacity. Use Proline products 6070-2 and 6070-4 or
Remove all traces of oxidation (rust), then clean with Metal Plus	Adhero Plus 290-2 and 290-4, available in more than 30
467 , metal conditioner.	colours.
Interior wood: The surface must be sanded with a #80 or #100	
grit sandpaper to smoothen the surface.	If the surface to be primed is not mentioned, please
	contact an MF Paints distributor for further
	recommendations.
APPLICATION	recommendations. MAINTENANCE
APPLICATION This product is ready to be used and does not require dilution. Mix	MAINTENANCE
	MAINTENANCE
This product is ready to be used and does not require dilution. Mix	MAINTENANCE
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a	MAINTENANCE Allow a 15 day drying time before proceeding with a first
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale	MAINTENANCE Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover	Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion.
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and	Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion.
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with	Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion.
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with	Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion.
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with lukewarm soapy water following their use.	MAINTENANCE Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion.
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with lukewarm soapy water following their use. For spray application : Dilute with a maximum of 10% water.	MAINTENANCE Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion. STORAGE
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with lukewarm soapy water following their use. For spray application : Dilute with a maximum of 10% water. Pressure : 2000 to 2500 lb/in ^{2*}	MAINTENANCE Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion. STORAGE Store the paint in a dry area and maintain temperature
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with lukewarm soapy water following their use. For spray application : Dilute with a maximum of 10% water. Pressure : 2000 to 2500 lb/in ^{2*}	MAINTENANCE Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion. STORAGE
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with lukewarm soapy water following their use. For spray application : Dilute with a maximum of 10% water. Pressure : 2000 to 2500 lb/in ^{2*} Nozzle : 0.015 – 0.019*	MAINTENANCE Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion. STORAGE Store the paint in a dry area and maintain temperature
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with lukewarm soapy water following their use. For spray application : Dilute with a maximum of 10% water. Pressure : 2000 to 2500 lb/in ^{2*} Nozzle : 0.015 – 0.019* *This data may vary depending on the brand of the equipment	MAINTENANCE Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion. STORAGE Store the paint in a dry area and maintain temperature
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with lukewarm soapy water following their use. For spray application : Dilute with a maximum of 10% water. Pressure : 2000 to 2500 lb/in ^{2*} Nozzle : 0.015 – 0.019* *This data may vary depending on the brand of the equipment manufacturer. WARRANTY	MAINTENANCE Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion. STORAGE Store the paint in a dry area and maintain temperature between 10°C and 30°C. CAUTION
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with lukewarm soapy water following their use. For spray application : Dilute with a maximum of 10% water. Pressure : 2000 to 2500 lb/in ^{2*} Nozzle : 0.015 – 0.019* *This data may vary depending on the brand of the equipment manufacturer. WARRANTY This product will give full satisfaction if applied according to the	MAINTENANCE Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion. STORAGE Store the paint in a dry area and maintain temperature between 10°C and 30°C. CAUTION • Keep away from children's reach
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with lukewarm soapy water following their use. For spray application : Dilute with a maximum of 10% water. Pressure : 2000 to 2500 lb/in ^{2*} Nozzle : 0.015 – 0.019* *This data may vary depending on the brand of the equipment manufacturer. WARRANTY This product will give full satisfaction if applied according to the manufacturer's instructions. Manufacturer liability is limited to	MAINTENANCE Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion. Store the paint in a dry area and maintain temperature between 10°C and 30°C. CAUTION • Keep away from children's reach • Keep lid closed when not in use
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with lukewarm soapy water following their use. For spray application : Dilute with a maximum of 10% water. Pressure : 2000 to 2500 lb/in ^{2*} Nozzle : 0.015 – 0.019* *This data may vary depending on the brand of the equipment manufacturer. WARRANTY This product will give full satisfaction if applied according to the manufacturer's instructions. Manufacturer liability is limited to the replacement of the product and does not include manpower	MAINTENANCE Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion. STORAGE Store the paint in a dry area and maintain temperature between 10°C and 30°C. CAUTION • Keep away from children's reach
This product is ready to be used and does not require dilution. Mix well before use. Apply one coat or two if necessary. Allow a minimum drying time of 3 hours between each coat for pale colours and 6 hours for dark colours. In order to properly cover the surface, it is recommended to use a 15mm lint free roller and a quality nylon-polyester brush. Clean the brushes and rollers with lukewarm soapy water following their use. For spray application : Dilute with a maximum of 10% water. Pressure : 2000 to 2500 lb/in ^{2*} Nozzle : 0.015 – 0.019* *This data may vary depending on the brand of the equipment manufacturer. WARRANTY This product will give full satisfaction if applied according to the manufacturer's instructions. Manufacturer liability is limited to	MAINTENANCE Allow a 15 day drying time before proceeding with a first cleaning. Only use mild, non-abrasive cleaners and a soft cloth. Clean the surface using a light, circular motion. Store the paint in a dry area and maintain temperature between 10°C and 30°C. CAUTION • Keep away from children's reach • Keep lid closed when not in use

" Contact your municipality to dispose of the container in an environmentally-friendly manner "