



Pearl/Platine

Pearl/Platine Latex Acrylic

INTERIOR

DESCRIPTION

Latex Plus 130 is an acrylic latex Pearl/Platinum finish paint designed for interior application. This paint is easy to apply, very low spattering and fast dry. Latex Plus 130 can be used for residential and commercial projects.

USE

Latex Plus 130 should be applied to properly prepared and primed surfaces. It is recommended for doors and mouldings, cabinets, kitchens. It is also recommended for refreshing previously painted surfaces. The gloss allows soft cleaning.

ADVANTAGES

- Easy to apply
- Controlled spattering
- Good leveling
- Low VOC

LIMITATIONS

- Avoid application at temperatures below 10 ° C
- Do not use on floors
- > Do not mix with other paints
- Not designed to seal surfaces with bleeding

TECHNICAL DATA

Resin		Latex Acrylic	
Color		bases	
Solvent		Water	
Flash Point		N/A	
Inflammability		N/A	
Solids by weight		47	%
Solids by volume		35	%
voc		<50	g/l
Gloss	60°	15-20	%
Sheen	85°	40-50	%
The value is measured from the	white. It may vary depe	ending on the color	
Standards	N/A		

APPLICATION DATA

Spreading Rate				37-46 m ²		
May vary depending on the surface porosity				(400-500sqft)	gallon 	
Film Thickness	Wet			3,2-4,0	mils 	
	Dry			1,12-1,40	mils	
Drying Time*	Tack free			30	min	
	Recoat			4-8	hours	
	Cleaning			30	days	
	Final cure			30	days	
Application	Brush			1		
	Roller			10	mm	
	Spray Airless (Nozzle(0,015-0,019)*			2000-2500	lb/sqin	
*This data may vary dependi	ng on the equipmen	t of a manufact	urer			
Exterior application and condition				N/A		
Storage	Temperature between			10 et 30	°C	
Tinted Based	Format					
	946ML	3,78L	18,9L			
130-0 White	√	V				
130-1 Base P	1	V		max. 2 oz of colorant/3,78 L		
130-2 Base M	1	V		max. 5 oz of colorant/3,78 L		
130-4 Base D	1	V		max. 8 oz of colorant/3,78 L		
130-5 Base A	V	$\sqrt{}$ $\sqrt{}$ max. 12 oz of colorant/3,78				





Pearl/Platine Latex Acrylic

130

INTERIOR

SURFACE PREPARATION

The surface should be dry and clean, free from dust, oil, grease, rust and soap. On painted surface, it is recommended to clean with a degreaser (TSP) in order to remove any contaminant that could interfere with the adhesion and/or the full cure of the product. Rinse the entire surface thoroughly. Surfaces must be well sanded and dusted.

Presence of mold: Clean the affected area with a mixture of 1 part bleach to 3 parts of water. Rinse with clean water before it dries the entire surface thoroughly and let it dry.

Flaking or peeling: Remove mechanically the weakened paint, then sand the surface to make it even. A repair compound should be used to fill holes and uneven surfaces. Sand with # 150 grit sandpaper.

New Drywall: To avoid creating an unwanted texture on the drywall sheet, joint compound should not be sanded excessively.

Concrete / Masonry: Allow concrete / masonry to cure at least 30 days before painting.

Aluminum, galvanized and interior ferrous metal: Remove mechanically the oxidation (rust), then clean with the 467, Conditioner for metal.

Wood: The surface should be sanded with # 80 or # 100 grit sandpaper to improve adhesion.

RECOMMENDED PRIMERS

New Drywall: Apply Latex Plus 170

Concrete/block / rough brick: Apply Proline 6006 Block Filler to seal and level the texture of the concrete blocks

Wood without bleeding: Apply Protico 270

Wood with bleeding such as (cedar, redwood, exotic, plywood, recomposed and glued wood and any wood with bleeding): Apply one to two coats of Block Plus 296 alkydhased

WARNING: WOOD IS A NATURAL MATERIAL AND ALTHOUGH IT IS TREATED, BLEEDING MAY RECAP OVER TIME.

Pine knots: Seal pine knots with Stop Plus 298. Aluminum, galvanized metal: Adhero Plus 290 Interior metal ferrous not rusted: Adhero Plus 297 Latex paint high gloss: Portico 270

Alkyd paint: one coat of Adhero Hybrid 297.

Dark Colours: Some dark colors may require the application of a primer tinted in a dark color to improve opacity. Use the products the Adhero Plus 290-2 and 290-4

APPLICATION

This product is ready to use and does not require dilution. Mix well before use. Apply two coats of paint. Allow 4 hours drying time between coats for light colors and 8 hours for dark colors. In order to properly cover the surface, it is recommended to use a 10 mm lint free roller and a quality nylon-polyester brush. Clean rollers and brushes with warm soapy water after using them.

For spray application: Maybe diluted with a maximum of 10% water

Pressure: 2000 to 2500 lb/sqin*

Nozzle: 0.015 – 0.019*

*This data may vary depending on the brand of the equipment manufacturer

MAINTENANCE

The paint requires a minimum drying time of 30 days before proceeding with a first cleaning. It is not designed for recurrent cleaning. Use only water, and a soft cloth. Clean the surface with a light and circular movement.

WARRANTY

This product will give full satisfaction if applied according to the manufacturer's instructions. Manufacturer's liability is limited to the replacement of the product and does not include manpower if found defective upon inspection

CAUTION

- Keep away from children's reach
- Keep lid closed when not in use
- Avoid freezing

CONTACT YOUR MUNICIPALITY TO DISPOSE OF THE CONTAINER IN AN ENVIRONMENTALLY-FRIENDLY MANNER