

## **Technical Data Sheet**

# 100% Acrylic Flat Black

**DRYFALL PAINT** 

### DESCRIPTION

A latex 100% acrylic based dryfall paint developed for spraying factory and warehouse ceilings.

CHARACTERISTICS	TECHNICAL INF	ORMATIO	N	
When applied at a height exceeding 18 feet, with less than 50% humidity level, any dryfall paint particles that have fallen to the floor may be swept away with a broom or vacuumed.	Drying Time	Recoat: 4	hours	To touch: 1 hour
This paint develops a chemical bond with the metal which		At 25° Celsius Relative humidity at 50%		
makes it extremely difficult to scratch down to bare metal.  This latex based product emits a very faint odour and is not a	Surface Coverage	70 m² (750 pi²) for steel deck ceilings with ceiling joists		
fire hazard.	(for 946 ml)	140 m² (1500 pi²) for a flat ceiling		
This dryfall paint will prevent flash rust from appearing on the surface during the application.	Cleaning	Lukewarm soapy water  None		
ouridoo during the approaction	Dilution			
Not a health hazard This paint does not contain crystalline silica.	Solids by Weight	48%		
	Solids by Volume	36%		
	voc	< 150 g/L		
		60°	2%	
	GLOSS	85°	3%	
	Flat	May vary according to the texture of surface to which it will be applied on		
TINTING BASES FORMATS	STANDARDS			
Black 753-0 946ml 3.78L 18.9L X				
COLOURS				
Black				
USE	LIMITATIONS			
- For interior use	<ul> <li>Do not apply if temperature is below 10°C</li> <li>Will not protect against rust in a humid area</li> </ul>			
Developed for galvanized steel or other metal ceilings with more than 18 feet high				
Can be used on bare or painted surfaces     Suitable for both commercial or institutional projects	ing on the height of the ceiling, it is ble to cover the floor, when the relative			
	humidity is higher than 50%.			

#### **SURFACE PREPARATION**

The surface must be dry and clean, without dust, oil, grease, rust and soap. On painted surfaces, it is recommended to clean with T.S.P. (trisodium phosphate) in order to eliminate any contaminant that might harm the adhesion or the hardening of the product. Glossy surfaces must be sanded and dusted before painting.

#### SUGGESTED PRIMER

No primer required.

#### **APPLICATION**

Stir thoroughly before applying. It is important to keep the moisture content below 50% throughout the application. This is to keep the dry fall properties at 18 feet.

WARRANTY	CAUTION
This product will give full satisfaction if applied according to the manufacturer's instructions. Manufacturer's liability is limited to the replacement of the product and does not include manpower if found defective upon inspection.	-Keep in a dry area between 10° C-30° C

Dispose of the container in an environmentally-friendly manner.