

## SAFETY DATA SHEET (SDS)

	S	Section 1. Identification			
Product identifier 1060-0					
Other means of identification		que Stain			
Recommended use and restri		or Wooden Surfaces			
Initial supplier identifier         MF Paints Inc. 1605 Dagenais Boulevard W, Laval, QC H7L 5A3 T:(450) 628-3831					
	Emergency telephone number/restriction on use Canada – CANUTEC 24 hour number 613-996-6666				
		on 2. Hazard identification			
Classification of bazardous n					
Classification of hazardous product (name of the category or subcategory of the hazard class) Flammable liquid (Category 3)					
Skin irritation (Category 2)					
Eye irritation (Category 2A)					
Specific target organ toxicity –	single exposure (Category 3)	. Central nervous system			
Carcinogenicity (Category 2)		,			
Reproductive toxicity (Categor	v 2)				
		tements and precautionary statements of th	e category/subcategory)		
		······································	······································		
Danger					
H226 Flammable liquid and va H315 Causes skin irritation.	pour.				
H319 Causes serious eye irritat	ion				
H336 May cause drowsiness on					
H351 Suspected of causing car					
H361 Suspected of damaging f					
1 0 0	2	ndle until all safety precautions have been rea	d and understood P210 Keen away from		
		urces. No smoking. P240 Ground and bound of			
		g tools. P243 Take action to prevent sta			
		ice thoroughly after handling. P271 Use only o			
		on. $P303 + P361 + P353$ IF ON SKIN (or hair			
		wash with plenty of water. P332 + P313 IF Sk			
		wash it before reuse. P305 + P351 + P338 IF I			
		to do. Continue rinsing. P337 + P313 If eye in			
P304 + P340 IF INHALED: Remove person to fresh air and keep comfortable for breathing. P312 Call a doctor if you feel unwell P308 + P313 IF					
exposed or concerned: Get medical attention. P370 + P378 In case of fire: Use carbon dioxide, chemical powder agent and appropriate foam to					
extinguish. P403 + P233 + P23	35 Store in a well-ventilated p	blace. P405 Store locked up. P501 Dispose of	contents/container into safe container in		
accordance with local, regional or national regulations.					
Other hazards known	READ INSTRUCTIONS B	EFORE USING. DANGER OF COMBUS	TION. Keep out of reach of children.		
	Materials such as rags used	with this product may begin to burn by thems	elves. After use, put rags in water or lay		
	flat to dry, then discard.				
Section 3. Composition/information on ingredients					
Chemical name (common name/synonyms)		CAS number or other	Concentration (%)*		
Medium aliphatic solvent naph	tha	64742-88-7	< 10		
Titanium dioxide		13463-67-7	< 30		
T-Butyl acetate		540-88-5	< 10		
Octamethylcyclotetrasiloxane		556-67-2	< 20		
Stoddard solvent		8052-41-3	< 10		
Linseed oil		66071-03-2	< 5		
Silica crystalline, Quartz		14808-60-7	< 0.1		
* Statement - This safety data sheet provides concentration range(s) instead of the actual concentration(s) considered trade secret(s).					

	PRODUCT IDENTIFIER – 1060- DATE & VERSION – AUGUST 14, 2018 VERSION 0		
Inhalation	IF INHALED: Remove person to fresh air and keep comfortable for breathing. Call a doctor if you feel unwell.		
Ingestion	IF SWALLOWED: Immediately call a doctor. DO NOT INDUCE VOMITING. NEVER give anything by mouth if v		
	rapidly losing consciousness, or is unconscious or convulsing. Rinse mouth thoroughly with water. Have victim drink two		
Skin contact	glasses of water. If vomiting occurs naturally, have victim lean forward to reduce risk of aspiration.		
Skill contact	IF ON SKIN: wash with plenty of water. (15-20 minutes). IF SKIN irritation or rash occurs: Get medical attention. Take o contaminated clothing and wash it before reuse.		
Eye contact	IF IN EYES, Rinse cautiously with water for several minutes (15-20). Remove contact lenses, if present and easy to do. Contin		
Lje contact	rinsing. If eye irritation persists: Get medical attention.		
Most important	symptoms and effects (acute or delayed) Causes skin irritation. Causes serious eye irritation.		
	mediate medical attention/special treatment In all cases, call a doctor. Do not forget this document.		
	Section 5. Fire-fighting measures		
Specific hazards	of the hazardous product (hazardous combustion products)		
	d other irritant/toxic gases and fumes.		
	uitable extinguishing media		
	se carbon dioxide, chemical powder agent and appropriate foam to extinguish.		
	re equipment and precautions for fire-fighters		
	tating/toxic smoke and fumes may be generated. Do not enter fire area without proper protection. Firefighters should wear prope		
	ent and self-contained breathing apparatus with full facepiece. Shield personnel to protect from venting, rupturing or bursting cans.		
	from fire area if it can be done without risk. Water spray may be useful in cooling equipment and cans exposed to heat and flame.		
Wove containers i	Section 6. Accidental release measures		
Dancanal nuccou			
	tions, protective equipment and emergency procedures area until completion of clean-up. Ensure clean-up is conducted by trained personnel only. All persons dealing with clean-up shoul		
	area until completion of clean-up. Ensure clean-up is conducted by trained personnel only. All persons dealing with clean-up shoulate protective equipment (See Section 8).		
	terials for containment and cleaning up		
	release. Stop the leak if it can be done safely. Contain and absorb any spilled liquid concentrate with inert absorbent material, the		
	a container for later disposal (see Section 13). Contaminated absorbent material may pose the same hazards as the spilled produc		
Notify the approp	riate authorities as required.		
	Section 7. Handling and storage		
Precautions for s			
	ective clothing/eye protection/face protection.		
	it is very important that engineering controls are operating, and that protective equipment requirements and personal hygien		
	g followed. People working with this chemical should be properly trained regarding its hazards and its safe use. Inspect container		
	handling. Label containers appropriately. Ensure proper ventilation. Avoid breathing dust/fume/gas/mist/vapours/spray. Avoi		
contact with eyes,	skin and clothing. Keep away from heat, sparks and flame. Avoid generating high concentrations of dusts, vapours or mists. Kee		
away from incon	patible materials (Section 10). Keep containers closed when not in use. Empty containers are always dangerous. Refer also		
Section 8.			
~			
Conditions for sa	ife storage, including any incompatibilities		
	afe storage, including any incompatibilities entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10		
Store in a well-ve	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10		
Store in a well-ve Inspect all incom	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of		
Store in a well-ve Inspect all incom	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks.		
Store in a well-ve Inspect all incom obstruction and a	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection		
Store in a well-ve Inspect all incom obstruction and a Control paramet	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values)		
Store in a well-ve Inspect all incom obstruction and a Control paramet Exposure limits:	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 13463-67-7 ACGIH – TLV-TWA 10 mg/m <sup>3</sup> & PEL-TWA 10 mg/m <sup>3</sup> ; DUST ACGIH – TLV-TWA 1 mg/m <sup>3</sup> & PEL-TWA		
Store in a well-ve Inspect all incom obstruction and a Control paramet Exposure limits: 0 mg/m <sup>3</sup> (respirable	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 13463-67-7 ACGIH – TLV-TWA 10 mg/m <sup>3</sup> & PEL-TWA 10 mg/m <sup>3</sup> ; DUST ACGIH – TLV-TWA 1 mg/m <sup>3</sup> & PEL-TWA te fraction) & 15 mg/m <sup>3</sup> (total dust); CAS 8052-41-3 – ACGIH – TLV-TWA 100 ppm & PEL-TWA 500 ppm; CAS 14808-60-		
Store in a well-ve Inspect all incom obstruction and a Control paramet Exposure limits: ( mg/m <sup>3</sup> (respirable ACGIH – TLV-T	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 13463-67-7 ACGIH – TLV-TWA 10 mg/m <sup>3</sup> & PEL-TWA 10 mg/m <sup>3</sup> ; DUST ACGIH – TLV-TWA 1 mg/m <sup>3</sup> & PEL-TWA te fraction) & 15 mg/m <sup>3</sup> (total dust); CAS 8052-41-3 – ACGIH – TLV-TWA 100 ppm & PEL-TWA 500 ppm; CAS 14808-60- WA 0.025 mg/m <sup>3</sup> & PEL-TWA 0.1 mg/m <sup>3</sup> ; CAS 540-88-5 ACGIH – TLV-TWA 200 ppm & PEL-TWA 200 ppm;		
Store in a well-ve Inspect all incom obstruction and a Control parame Exposure limits: 0 mg/m <sup>3</sup> (respirable ACGIH – TLV-T Appropriate eng	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 13463-67-7 ACGIH – TLV-TWA 10 mg/m <sup>3</sup> & PEL-TWA 10 mg/m <sup>3</sup> ; DUST ACGIH – TLV-TWA 1 mg/m <sup>3</sup> & PEL-TWA teraction) & 15 mg/m <sup>3</sup> (total dust); CAS 8052-41-3 – ACGIH – TLV-TWA 100 ppm & PEL-TWA 500 ppm; CAS 14808-60- WA 0.025 mg/m <sup>3</sup> & PEL-TWA 0.1 mg/m <sup>3</sup> ; CAS 540-88-5 ACGIH – TLV-TWA 200 ppm & PEL-TWA 200 ppm; ineering controls		
Store in a well-ve Inspect all incom obstruction and a Control parame Exposure limits: 0 mg/m <sup>3</sup> (respirable ACGIH – TLV-T Appropriate eng Use under well-ve	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks.  Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 13463-67-7 ACGIH – TLV-TWA 10 mg/m <sup>3</sup> & PEL-TWA 10 mg/m <sup>3</sup> ; DUST ACGIH – TLV-TWA 1 mg/m <sup>3</sup> & PEL-TWA 200 ppm; CAS 14808-60- WA 0.025 mg/m <sup>3</sup> & PEL-TWA 0.1 mg/m <sup>3</sup> ; CAS 540-88-5 ACGIH – TLV-TWA 200 ppm & PEL-TWA 200 ppm; ineering controls entilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below exposure		
Store in a well-ve Inspect all incom obstruction and a <b>Control parame</b> Exposure limits: 0 mg/m <sup>3</sup> (respirable ACGIH – TLV-T <b>Appropriate eng</b> Use under well-ve limits. Make eme	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 13463-67-7 ACGIH – TLV-TWA 10 mg/m <sup>3</sup> & PEL-TWA 10 mg/m <sup>3</sup> ; DUST ACGIH – TLV-TWA 1 mg/m <sup>3</sup> & PEL-TWA ters (biological dust); CAS 8052-41-3 – ACGIH – TLV-TWA 100 ppm & PEL-TWA 500 ppm; CAS 14808-60- WA 0.025 mg/m <sup>3</sup> & PEL-TWA 0.1 mg/m <sup>3</sup> ; CAS 540-88-5 ACGIH – TLV-TWA 200 ppm & PEL-TWA 200 ppm; incering controls entilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below exposure regency eyewash stations, safety/quick-drench showers, and washing facilities available in work area.		
Store in a well-ve Inspect all incom obstruction and a Control paramet Exposure limits: 0 mg/m <sup>3</sup> (respirable ACGIH – TLV-T Appropriate eng Use under well-ve limits. Make eme Individual prote	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 13463-67-7 ACGIH – TLV-TWA 10 mg/m <sup>3</sup> & PEL-TWA 10 mg/m <sup>3</sup> ; DUST ACGIH – TLV-TWA 1 mg/m <sup>3</sup> & PEL-TWA e fraction) & 15 mg/m <sup>3</sup> (total dust); CAS 8052-41-3 – ACGIH – TLV-TWA 100 ppm & PEL-TWA 500 ppm; CAS 14808-60- WA 0.025 mg/m <sup>3</sup> & PEL-TWA 0.1 mg/m <sup>3</sup> ; CAS 540-88-5 ACGIH – TLV-TWA 200 ppm & PEL-TWA 200 ppm; ineering controls entilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below exposur rgency eyewash stations, safety/quick-drench showers, and washing facilities available in work area. ction measures/personal protective equipment		
Store in a well-ve Inspect all incom obstruction and a Control paramet Exposure limits: 0 mg/m <sup>3</sup> (respirable ACGIH – TLV-T Appropriate eng Use under well-ve limits. Make eme Individual prote Respiratory prote	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 13463-67-7 ACGIH – TLV-TWA 10 mg/m <sup>3</sup> & PEL-TWA 10 mg/m <sup>3</sup> ; DUST ACGIH – TLV-TWA 1 mg/m <sup>3</sup> & PEL-TWA e fraction) & 15 mg/m <sup>3</sup> (total dust); CAS 8052-41-3 – ACGIH – TLV-TWA 100 ppm & PEL-TWA 500 ppm; CAS 14808-60- WA 0.025 mg/m <sup>3</sup> & PEL-TWA 0.1 mg/m <sup>3</sup> ; CAS 540-88-5 ACGIH – TLV-TWA 200 ppm & PEL-TWA 200 ppm; ineering controls entilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below exposur rgency eyewash stations, safety/quick-drench showers, and washing facilities available in work area. ction measures/personal protective equipment ction is required if the concentrations are higher than the exposure limits. Use a NIOSH approved respirators if the exposure limit		
Store in a well-ve Inspect all incom obstruction and a Control paramet Exposure limits: 0 mg/m <sup>3</sup> (respirable ACGIH – TLV-T Appropriate eng Use under well-ve limits. Make eme Individual prote Respiratory prote	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks.  Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 13463-67-7 ACGIH – TLV-TWA 10 mg/m <sup>3</sup> & PEL-TWA 10 mg/m <sup>3</sup> ; DUST ACGIH – TLV-TWA 1 mg/m <sup>3</sup> & PEL-TWA e fraction) & 15 mg/m <sup>3</sup> (total dust); CAS 8052-41-3 – ACGIH – TLV-TWA 100 ppm & PEL-TWA 500 ppm; CAS 14808-60-WA 0.025 mg/m <sup>3</sup> & PEL-TWA 0.1 mg/m <sup>3</sup> ; CAS 540-88-5 ACGIH – TLV-TWA 200 ppm & PEL-TWA 200 ppm; incering controls entilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below exposur gency eyewash stations, safety/quick-drench showers, and washing facilities available in work area.		
Store in a well-ve Inspect all incom obstruction and a <b>Control paramet</b> Exposure limits: 0 mg/m <sup>3</sup> (respirable ACGIH – TLV-T <b>Appropriate eng</b> Use under well-ve limits. Make eme <b>Individual prote</b> Respiratory prote are unknown. Che	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 13463-67-7 ACGIH – TLV-TWA 10 mg/m <sup>3</sup> & PEL-TWA 10 mg/m <sup>3</sup> ; DUST ACGIH – TLV-TWA 1 mg/m <sup>3</sup> & PEL-TWA e fraction) & 15 mg/m <sup>3</sup> (total dust); CAS 8052-41-3 – ACGIH – TLV-TWA 100 ppm & PEL-TWA 500 ppm; CAS 14808-60 WA 0.025 mg/m <sup>3</sup> & PEL-TWA 0.1 mg/m <sup>3</sup> ; CAS 540-88-5 ACGIH – TLV-TWA 200 ppm & PEL-TWA 200 ppm; incering controls entilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below exposur rgency eyewash stations, safety/quick-drench showers, and washing facilities available in work area. ction measures/personal protective equipment ction is required if the concentrations are higher than the exposure limits. Use a NIOSH approved respirators if the exposure limit emically protective gloves (impervious), and other protective clothing to prevent prolonged or repeated skin contact, must be work		
Store in a well-ve Inspect all incom obstruction and a <b>Control paramet</b> Exposure limits: 0 mg/m <sup>3</sup> (respirable ACGIH – TLV-T <b>Appropriate eng</b> Use under well-ve limits. Make eme <b>Individual prote</b> Respiratory prote are unknown. Cho during all handlin	entilated place. Keep container tightly closed. Keep cool. Store locked up. Store away from incompatible materials (Section 10 ing containers to make sure they are properly labelled and not damaged. Storage area should be clearly identified, clear of ccessible only to trained personnel. Inspect periodically for damage or leaks. Section 8. Exposure controls/Personal protection ters (biological limit values or exposure limit values and source of those values) CAS 13463-67-7 ACGIH – TLV-TWA 10 mg/m <sup>3</sup> & PEL-TWA 10 mg/m <sup>3</sup> ; DUST ACGIH – TLV-TWA 1 mg/m <sup>3</sup> & PEL-TWA e fraction) & 15 mg/m <sup>3</sup> (total dust); CAS 8052-41-3 – ACGIH – TLV-TWA 100 ppm & PEL-TWA 500 ppm; CAS 14808-60- WA 0.025 mg/m <sup>3</sup> & PEL-TWA 0.1 mg/m <sup>3</sup> ; CAS 540-88-5 ACGIH – TLV-TWA 200 ppm & PEL-TWA 200 ppm; ineering controls entilated conditions. Local exhaust ventilation system is recommended to maintain concentrations of contaminants below exposur rgency eyewash stations, safety/quick-drench showers, and washing facilities available in work area. ction measures/personal protective equipment ction is required if the concentrations are higher than the exposure limits. Use a NIOSH approved respirators if the exposure limit		



Section 9. Physical and chemical properties					
Appearance, physical state/colour Liquid	Vapour pressure	Not available			
Odour Characteristic	Vapour density	Not available			
Odour threshold Not available	Relative density	1.171 g/L			
<b>pH</b> Not available		vailable			
Melting/freezing point         Not available		<b>it - n-octanol/water</b> Not available			
Initial boiling point/range Not available	Auto-ignition temperature         Not available				
Flash point     25°C closed cup	Decomposition temperature Not available				
Evaporation rate     Not available	Viscosity 209 cSt @ 40°C				
Flammability (solids and gases) Not available	VISCOSICY 209 CS				
Upper and lower flammability/explosive limits Not available	Other None kno				
Section 10. Stability and reactivity					
Reactivity					
Does not react under the recommended storage and handling conditions prescri	bed.				
Chemical stability					
Stable under the recommended storage and handling conditions prescribed.					
Possibility of hazardous reactions					
Keep away from heat, hot surfaces, sparks, open flames and other ignition so	urces. No smoking. T	ake action to prevent static discharges.			
Conditions to avoid (static discharge, shock or vibration)					
Keep away from heat, hot surfaces, sparks, open flames and other ignition so	urces. No smoking. T	ake action to prevent static discharges. Materials			
such as rags used with this product may begin to burn by themselves. After u					
Incompatible materials	, 8				
Oxidizing materials; etc.					
Hazardous decomposition products					
None known					
Section 11. Toxicologi	ical information				
Information on the likely routes of exposure (inhalation, ingestion, skin a					
Causes skin irritation. Causes serious eye irritation. May cause drowsiness or o		f causing cancer. Suspected of damaging fertility			
or the unborn child.					
Symptoms related to the physical, chemical and toxicological characteris	stics				
Skin irritation, redness, stinging, pain; Eye irritation, redness, tearing; R		tion, coughing, shortness of breath, dizziness,			
drowsiness, nausea and headaches.		,			
Delayed and immediate effects (chronic effects from short-term and long	g-term exposure)				
Skin Sensitization - No data available; Respiratory Sensitization - No data av		utagenicity – No data available; Carcinogenicity			
- Ingredient listed by IARC, ACGIH, NTP or OSHA; Reproductive Toxici	ity - Possible; Specif	ic Target Organ Toxicity — Single Exposure –			
Possible; Specific Target Organ Toxicity — Repeated Exposure - No data a	vailable; Aspiration I	Hazard – No data available; Health Hazards Not			
Otherwise Classified – No data available.	_				
Numerical measures of toxicity (ATE; LD50 & LC50)					
None					
ATE not available in this document.					
Section 12. Ecologic					
<b>Ecotoxicity (aquatic and terrestrial information)</b> No data available for	the product.				
Persistence and degradability No data available					
Bioaccumulative potential No data available					
Mobility in soil         No data available	Mobility in soil         No data available				
Other adverse effects No data available					
Section 13. Disposal considerations					
Information on safe handling for disposal/methods of disposal/contaminated packaging					
Dispose of contents/container into safe container in accordance with local, regional or national regulations.					
Section 14. Transport information					
UN number; Proper shipping name; Class(es); Packing group (PG) of the TDG Regulations					
UN1263; PAINT RELATED MATERIAL; CLASS 3; PG III					
UN number; Proper shipping name; Class(es); Packing group (PG) of the IMDG (maritime)					
UN1263; PAINT RELATED MATERIAL; CLASS 3; PG III					
UN number; Proper shipping name; Class(es); Packing group (PG) of the IATA (air)					
UN1263; PAINT RELATED MATERIAL; CLASS 3; PG III					
Special precautions (transport/conveyance)         May also be shipped as a LIMITED QUANTITY in accordance with TDG.           Environmental baganda (IMDC or other)         None					
Environmental hazards (IMDG or other) None					
Bulk transport (usually more than 450 L in capacity)Possible					



Safety/health C	anadian regulations specifics	Refer to Section 2 for the appropriate classification. This product has been classified in accordance		
Salety/nearth C	anatian regulations specifics	with the hazard criteria of the Hazardous Products Regulations (HPR).		
Environmental	Canadian regulations specifics	Refer to Section 3 for ingredient(s) of the DSL		
Safety/health/environmental outside regulations specifics				
United States OSHA information: This product is regulated according to OSHA (29 CFR).				
United States CSHA information: This product is regulated according to OSHA (29 CFR). United States EPA (Environmental Protection Agency) information: 40 CFR Refer to the ingredients listed in Section 3 & Sections 12; 13 & 14.				
United States TCSA information: Refer to the ingredients listed in Section 3.				
California Proposition 65: This product contains an ingredient known to the State of California to cause cancer or other reproductive harm.				
Section 16. Other information				
Date of the late	st revision of the safety data shee			
References	Safety Data Sheets from manufacturer/supplier & from Canadian Centre for Occupational Health and Safety, CCOHS.			
Abbreviations	~~~~~			
ACGIH	American Conference of Governmental Industrial Hygienists			
ATE	Acute toxicity estimate			
CAS	Chemical Abstract Service			
DSL	Domestic Substance List			
IARC	International Agency for Research on Cancer			
IATA	International Air Transport Association			
IMDG	International Maritime Dangerous Goods Code			
LC	Lethal concentration			
LD	Lethal Dosage			
NIOSH	National Institute for Occupational Safety and Health			
NTP	National Toxicology Program (U.S.A.)			
OSHA	Occupational Safety and Health Administration (U.S.A.)			
PEL	Permissible Exposure Limit			
STEL	Short-term Exposure Limit			
TDG	Transport of dangerous goods in Canada			
TLV	Threshold Limit Value			
TSCA	Toxic Substances Control Act			
TWA	Time Weighted Average			
	WHMIS Workplace Hazardous Materials Information System			
	To the best of our knowledge, the information contained herein is accurate. However, neither the above named supplier nor any of its subsidiaries assumes any liability			
whatsoever for the accuracy or completeness of the information contained herein. Final determination of suitability of any material is the sole responsibility of the				
	user. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that these are the only hazards that exist.			
the only hazalus u	iut chist.			