# **DRYFALL PAINT**

INTERIOR

**755** 

Flat, White Alkyd

### **DESCRIPTION**

**755** is a dryfall paint Alkyd based for spraying application to ceilings. The 755 paint has a matte finish. It can be used in commercial or industrial ceilings.

### **USE**

This paint should be sprayed on interior ceilings with a minimum height of 10 feet. It can be applied to properly prepared and primed surfaces, on new or previously painted surface, such as gypsum, wood, concrete, masonry, galvanized metal and metal structures.

# **ADVANTAGE**

- > Protect against flash rust issue
- Dryfall paint can be swept on the floor like dust when applied at a minimum of 10 feet high and less than 50% humidity. The floor should also be dry
- > Ideal for corrugated galvanized metal ceilings
- Ideal for non-rusting metal structures
- > Ideal for concrete, gypsum, wood ceilings
- Very good adhesion

## **LIMITATION**

- Avoid application at temperatures below 10 ° C
- Will not protect against rust in humid aera
- In case the relative humidity exceeds 50% during the application and depending on the height of the building, it is recommended to cover the floors
- Not designed to be applied with a roller or brush
- > some new galvanized metals may contain contaminants on the surface which can affect the adhesion. It is recommended to perform a test patch adhesion.

### **TECHNICAL DATA**

Resin			Alkyd	
Colour			White	
Flash Point			30	°C
Inflammability			oui	
Weight Solids			71	%
Volume Solids	***************************************		45	%
cov			<400	g/l
Gloss	60°		2,4	%
Sheen	80°		5	%
Standards	MPI	Certified Category #55		•

### **APPLICATION DATA**

At 25° Celsius					
Relative humidity at 50%					
May differ depending on the colour					
Spreading Rate	Corrugated ceiling with load-bearing beams		26-38 m <sup>2</sup>	18,9 L	
May vary depending on the surface porosit			(275-400sqft)		
	Flat Ceiling				18,9 L
				52-75 m2	
			(550-800sqft)		
These values do not include applicati	on loss. Several fact	tors can vary the s	pread rate such		
as presence and number of beams, th	e complexity of the	structure as well	as the porosity of		
the surface.					
Theoretical Coverage	720 sqft per ga	llon @ 1mil dry			
Dry Time	Tack Free			15-30	min
	Recoat		30	min	
	Cleaning		N/A		
Application	Brush			N/A	
	Roller		N/A	mm	
	Spray (Nozzle 0	,015-0,019)*	2200-2800	lb/sqin	
*This data may vary depending on the	equipment of a man	ufacturer			
Exterior application and cond	N/A				
Storage	Temperature		10 et 30	°C	
Base		Format			
	946ml	3,78L	18,9L		
755-0 White			V		



# **DRYFALL PAINT**

INTERIOR

**755** 

Flat, White Alkyd

#### PREPARATION SURFACE

The surface should be dry and clean, free from dust, oil, grease, rust and soap. On an already painted surface, clean with a degreaser (T.S.P) to remove any contaminant that may interfere with the adhesion and curing of the product. Rinse the entire surface thoroughly and allow it to dry. Surfaces must be well sanded and dusted before painting.

**Presence of mold:** Clean the affected area with a mixture of 1 part bleach to 3 parts of water. Rinse the entire surface thoroughly and allow it to dry.

**Concrete / Masonry:** Allow concrete / masonry to harden at least 30 days before painting.

**Aluminum, galvanized metal:** Remove all traces of oxidation (rust), then clean with a degreaser.

**Ferrous metals:** Clean the surface with a cleaner / degreaser (SSPC-SP1), then scrub the surface with a mechanical (SSPC-SP2) or electric (SSPC-SP3) tool to remove all traces of rust.

# **RECOMMENDED PRIMERS**

**Gypsum:** No primer is required

Concrete / masonry: No primer is required

Wood (No knots or tannins): No primer is required.

Pine knots: Seal pine knots with Stop Plus 298.

Red Cedar and Redwood: Apply one coat of Block Plus

and the the transfer of the court of Block

296, alkyd based.

**Aluminum, Galvanized Metal:** No primer is required.

(See limitations)

Ferrous metals: On rust, apply Iso-Rust 4350 gray or

4370 steel red or 4700-0 white as a first coat

Latex paint: No primer is required.

Alkyd Paint / Gloss Surface: No primer is required.

# **APPLICATION**

Mix well before use. It is important to keep the humidity below 50% throughout the application so that the fallout is always dry at the recommended height.

#### WARRANTY

This product will give complete satisfaction if applied according to the manufacturer's instructions. In the event that this is found to be defective after inspection, the manufacturer's liability is limited to replacement of the product and does not include labor during application.

### **CAUTION**

- > Keep out of the reach of children
- Keep container closed when not in use
- Avoid freezing

Contact your municipality to dispose of containers and surpluses in an environmentally friendly manner.